

Ch. Chaviaris - D. Papadios & Co  
 Metal Products Industry  
 Construction of Chimneys and Components  
 Factory: 20th km Thessaloniki - Serres,  
 P.O. 127, P.C. 57200, Langadas Thessaloniki Greece  
 Phone: +30 23940 61275, +30 23940 61504, Fax: +30 23940 61094  
 www.technometalhellas.gr e-mail: info@technometalhellas.gr

## DECLARATION OF CONFORMITY & PRODUCT INFORMATION

Requirements for metal chimneys Part 1: System chimney products DIN EN 1856-1:2009 and EN 1856-2:2009

**Commercial name:** TechnoGos 304 CE®  
**Person in charge:** Dimitris Papadios  
**Number Certificate:** 1922 - CPR - 0953  
**Date of Publication:** 21.12.2017  
**Product:** Single Wall, Chimney System and Fittings,  
 Metal liners and Connecting Flu pipes  
 Stainless Steel 1.4301 - AISI 304 BA - Thicknesses  $\geq 0,40$  mm

Identification of accompanying documentation to EN 1856-1 and EN 1856-2.

Metal chimneys with silicone gasket:

EN 1856-1, T200, P1, W, V2, L20040, G(100), Ø80-500

Metal chimneys without silicone gasket:

EN 1856-1, T400, N1, D, V2, L20040, G(150), Ø80-500

EN 1856-2, T400, N1, D, V2, L20040, G(250), Ø80-500

Product	
Standard Number	
Temperature Level	
Pressure Level	
Condensate Resistance (W: wet - D: dry)	
Corrosion Resistance Class	
Flu Liner Material Specification	
Sootfire Resistance (G: yes - O: no) Distance to combustible material in (mm)	
Nominal diameter (Ø) (inner tube) in mm	

### Properties of a multi-wall metal chimney system

**Compressive strength:** Maximum load (Installing instructions)

**Flow resistance:** Average roughness: 1,0 mm, according to DIN EN 13384-1  
 (Installing instructions)

**Thermal resistance:** 0,501 m<sup>2</sup>K/W

**Flexural strength angular assembly:** Maximum length between two supports: 3m at 90°

**Tensile strength:** (Installing instructions)

**Wind load:** free standing end above last fixation:  $\leq 2$ m up to Ø500 mm (Installing instructions)

**Maximum distance between vertical supports:** 2m

**Freeze-thaw resistance:** Yes

**Cleaning:** The chimney system may only be cleaned by a SPECIALIZED PERSONNEL.